



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program October 1, 2009

Reviewed: PTB

Mine Name: Clark 1/Emeryide	Permit Number: S/015/0053
Operator Name: Robert Clark	Inspection Date: 08/20/2009
Inspector(s): Brett Gregory for Wayne Western	Time: 3:30 pm
Other Participants: None	Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$5,400

Permit fee: Current

Purpose of Inspection: This was a routine inspection of the site.

Inspection Summary:

- 2) There are a few loose pieces of garbage that can be cleaned up, although nothing too significant.
- 3) A sediment trap should be constructed in one of the photographs documented below, and the other trap shown needs minor maintenance.
- 5) Deep ruts have formed on the haul road coming up from the portal. I would suggest the installation of a water bar and ditch to control runoff.

Conclusions and Recommendations: There really is very little work needing to be done on site. Other than the minor trash to be removed and rain runoff issues, the site is stable.

DOGM will continue to monitor the site.

Inspector's Signature

BG:vs

cc: Bob Clark, Operator
Chris Conrad, Price BLM

P:\GROUPS\MINERALS\WPM015-Emery\S0150053-RobertClark\inspections\insp-08202009.doc





A sediment trap or something like it should be installed here.



Sediment trap fallen under disrepair.



Trash can be cleaned up.



More trash.



Access road.



Camper left on site.



Mine portal.



The road shown here exiting is developing deep ruts.